


Shiloh Church Road Survey Data Map

Date: 7/25/19

Area: Rad Storage Conex

Smear	α (dpm)	β (dpm)
1	0	-20
2	-1	-61
3	0	-61



LEGEND: # : Smear ### : Exposure Rate ($\mu\text{R}/\text{hour}$) - - - - - : Rad Rope

Surveyed by: [Redacted]

Date: 7/25/19

Comments: Background exposure rate at main gate was 9.4 $\mu\text{R}/\text{hour}$. Exterior exposure rates collected with doors closed. All exposure rate readings collected from about 2 feet above ground. Smears 1 and 2 collected from floor. Smear 3 collected from wall.

Reviewed by: [Redacted]

Date: 7/25/19